



Product Change Notice

PCN NO: G08-0000049

Issue Date: 25th July,2023

Product(s) affected:

Model Name	Description
WMP-105	Lan chip & power management IC change to new solution.

Reasons of Change:

Due to Intel LAN chip (i211AT) & TI PMIC shortage update MB revision to change LAN chip & power design.

Description of Change:

Item	Before change	After change	Impacts
Version	A	D	
LAN chip	Intel i211AT	Realtek RTL8111H	Driver update & image update
Power management	TI PMIC	discrete design	None

Impacts on Quality or Reliability:

QA: None

Customer Impacts and Recommended Actions:

Need driver & image update

Contact information:

sales_support@wincomm.com.tw

Sample Order/Implementation Date:

Ready to delivery date: 15th September /2023

Model Name	Part NO	Order to
As in product(s) affected list	Consult sales account manager for specific part number	sales_support@wincomm.com.tw

Customer Acknowledgement of Receive: Wincomm requests your acknowledgement of this notice. Please contact your sales manager to grant approval or further information. Wincomm will deem this change notice accepted unless specific accepted conditions are received via an email to your contact window within 30 days from the date of this notice issued.