



# Product Change Notice

PCN NO: G08-00000041

Issue Date: 11<sup>th</sup> March,2022

## Product(s) affected:

Model Name	Description
WLP-7B20-15;WLP-7E20-15;WLP-7F20-15; WLP-7G20-15;WLPM-915;WLPM-V15; WTP-8B66-15;WTP-8D66-15;WTP-9E66-15;WTP-9G66-15	Current 15" panel shortage, Phase in new panel as 2 <sup>nd</sup> source.

## Reasons of Change:

Current TIANMA, TM150TDSG71 panel shortage, Phase in AUO, G150XTN03.5 as 2<sup>nd</sup> source

## Description of Change:

Item	Before change	After change
Panel Vendor	TIANMA	AUO
Panel model	TM150TDSG71	G150XTN03.5
Display Mode	TN mode	TN mode
Contrast Ratio	800	800
Response Time	8ms	5.7ms
Brightness	450nits	350nits

## Impacts on Quality or Reliability:

No

## Customer Impacts and Recommended Actions:

No

## Contact information:

[sales\\_support@wincomm.com.tw](mailto:sales_support@wincomm.com.tw)

## Sample Order/Implementation Date:

Ready to deliver date: 11<sup>th</sup> March,2022

Model Name	Part NO	Order to
As in product(s) affected list	Consult sales account manager for specific part number	<a href="mailto:sales_support@wincomm.com.tw">sales_support@wincomm.com.tw</a>

**Customer Acknowledgement of Receive:** Wincomm requests your acknowledgement of this notice. Please contact your sales manager to grant approval or further information. Wincomm will deem this change notice accepted unless specific accepted conditions are received via an email to your contact window within 30 days from the date of this notice issued.